PE Number [	Date reported	Incident Start Date	Incident Start Time	Overall assessment of event	Event outcome Fin	nal Comment	Type of Incident	Description of Incident as reported to Environment Canterbury	No. Reports per Day COMPLETE	Activity Date CHECKED	Activity Type	Response
PE20142513	23/06/2014	23/06/2014	8:00	Event Substantiated	Written Warning		Earthworks/land use consents	I have recently been in the upper Mary Burn (Mackenzie basin) along the Braemar rd and discovered some significant damage to the banks of the river. These images were taken on the 19.06.2014. Local landowner explained that Rooneys were extracting large boulders to use as erosion control for Meridian. To access the Quarry which I understand is located on Braemar station they had to get their machine along Braemar rd. As understand it they got the machines in without any problems but on the way out decided to drive them through the river rather than use the adjacent Bridge. I observed the attached damage on the upper Mary Burn and was told that the machines also drove through the Irishmans Creek and Forks Stream. I think we need to investigate this incident in which a significant amount of sediment will have entered the streams.	,			
PE20112596	3/11/2011	3/11/2011	8:00	Event not Substantiated			Dust	Has phoned to complain about the dust that trucks are creating when they use Fraser Road after getting to and from a quarry on Fraser Road. Recently Rooney Earthmoving trucks have started using the road to get access to and from the quarry. I believe the quarry is located where CRC010324 was. Caller said that they used to use canola oil on the road to supress the dust from 'normal' traffic but now much bigger vehicles are using the road and the canola oil doesn't make much of a difference Could someone please look into this and give her a call? We weren't sun if this was something ECan could look into or whether it was a District Council matter. Diane said she had called TDC but they referred her to ECan.				
PE20120501	8/02/2012	8/02/2012	8:00	Event not Substantiated			Dust	Caller phoned to complain about a quarry. They have a consent with TDD but don't comply with the conditions (have told her to contact TDC abou this). She says that the dust from the trucks that go in and out of the property is terrible. They have also done blasting onsite several times. The caller wasn't sure whether they should be doing this or not.				
PE185408	16/05/2018	16/05/2018	8:00	Event not Substantiated	Referred Int/Ext	JH 28/05/2018: Send to CPW.	Unauthorised structure/disturbanc e	16/05/2018 02:09pm - Caller reported a quarrying operation in the Selwyn River near Hawkins Road, Hororata. They have a forestry operation at Lot 3 DP 78682. They are concerned about the works happening there and they have not been notified. The quarrying is happening on the same side of the River as the forestry block. There is a road running through the bed which they were not aware of. Site is causing water to pond and causing erosion of the forestry block. Would like someone to give them a call back about this.				
PE20120065	11/01/2012	11/01/2012	8:00	Event not Substantiated			Earthworks/land use consents	Customer concerned that potentially un-consented quarry has been operating for some time just off State Highway 82 near the Waimate Gorge. The site is near the corner of Kapua Road of State Highway 82 and is operated by Rooney Earth Moving. Customer would like to be contacted about this enquiry.	1			
PE183163	2/11/2017	2/11/2017	12:00	Event Substantiated	Is sto Provided Education ro dis the	11/17 Site v, 640 McLeans Rd. Rooneys Contracting are carting gravel from a ock on Ecan land. The haul oad is very dusty & as the trucks drive out onto McLeans Is Rd dust scharges across the rd onto s Steam Museum property. Rooney's will follow up	Dust	02/11/2017 03:23pm Caller y reports large amounts for dust being blown onto the McLeans Island Road by who he thinks was "Runnie's Truck and Trailers" tucks coming out of a site on Mcleans Island. Dust was noticed at 12pm-now and caller thought is almost caused an accident on McLeans Island Road. UPDATE 03/11/2017 - Through a discussion with the caller I confirmed the correct address that the trucks where coming out of causing dust issues.	1	3/11/2017	Pollution - Site Visit	Site visit
PE20144895	25/11/2014	25/11/2014	16:08	Event not Substantiated			Dust	Hello, the customer called at 1608 in regards to dust pollution and quarrying at the site of Lot 1 DP 22449 held by Rooneys Holdings Limited. (EC101024). The customer said Rooneys were undertaking gravel extraction adjacent to their property boundary, which has caused issues with dust, noise and is affecting their day-to-day living. The customer then sent through a follow up email which has been TRIMed a C14C/211876. The customer wants this situation followed up, and woult like some information on whether Rooneys Holdings Limited holds a consent for gravel extraction at this site for being able to undertake it so close to the property boundary, and at the scale they are excavating. Cheers.	t 1 d			