

## Corrections – Dave Stewart , Report 2B

- Table 1. Mt Cook minimum annual rainfall should be 1941mm not 4131mm
- Paragraph 102 Delete the words “Under 1:1 flow sharing...the MALF”(end of paragraph)
- Paragraph 119 Delete the words “Under 1:1 flow sharing...the MALF”(end of paragraph)
- Paragraph 181 Change Omarama swamp to Clifton Downs swamp
- Paragraph 213 last line change the word “less” to “more”
- Paragraph 270 second line should read “...an extra 100 l/s..” not 400 l/s
- Paragraph 328 Figure 9a of the SKM report is not appended as Figure 21. It can be supplied if the Commissioners so wish.