



Appendix 5





Looking upstream at principal diversion point from Waiau River. One cumec authorised to be diverted into old natural channel. Minor works necessary to maintain the open diversion. Fall is steep with rapidly flowing water which keeps the channel open. Channel is not deep, around 0.5 metres. It is a simple operation with a digger to keep the channel open to the main Waiau River channel.



Looking downstream at diversion channel. Very stable channel. Photographs taken 18/8/20.