

## **Springfield Partnership Limited images**

---

For photos 1 to 4, each of the top photos was taken on October 1 2020, the lower photos were taken a week later. They are a good example of the high and low levels of the lagoon and the manner in which it fluctuates regularly throughout the year.

Photo 1 – Top photo shows the Lagoon level caused by the Opihi River mouth being blocked by rough seas. The lower photo shows the Lagoon a week later. Both photos taken from Prattley Road looking east towards the sea.

Photo 2 – Lagoon taken from Prattley Road looking south

Photo 3 – Milford Lagoon Road looking east

Photo 4 – Milford Lagoon Road looking west.

Photo 5 – Taken looking upstream at the junction of the Burke Creek and the Orakipaoa Creek. The Orakipaoa creek follows the blue line. Burke Creek is straight ahead. This is trying to show that the Orakipaoa creek beyond this point does not fit the “High Naturalness water body” due to the fact that the Taumatakahu Stream no longer follows this course.

















